



BUCKET VIEW CORNER REMOVED (1 : 50)



A (1 : 5)

NOTES:

1. CUT END OF GROUSER AND POSITION AS PER DETAILED VIEW A.
2. DO NOT WELD THE LAST 70mm OF THE GROUSER BAR TO PREVENT HEAT DAMAGE TO CAST CORNER.
3. ENSURE PREHEAT OF 150°C PRIOR TO ANY WELDING PROCESS.



LOCKJAW G SERIES GROUSER BAR
PLACEMENT REFERENCE DRAWING

SCALE:
1:20

SIZE:
A4

DRAWN BY:
NEIL D.

DATE:
12/06/2018

DO NOT SCALE
ALL DIMENSIONS IN MILLIMETERS
ALL MODELS CONTAINED ARE PROVIDED AT
MMC CONDITION UNLESS INDICATED OTHERWISE



DWG No:
TMC0063

SHEET:
1:1

REVISION:
0